


CARINA II (\_T15\_)

10/1983 - 05/1988



MS -> 08/1984



4 73-02-291



2 103-02-202



2 103-02-202



4 73-02-291

MS 09/1984 ->



5 111-02-259



1 103-02-206



1 103-02-206



5 111-02-259

PS 09/1984 ->



5 111-02-259



3 103-02-210




3 103-02-210




5 111-02-259



6 53-02-296



LOWER



6 53-02-296

| Ref | ASHIKA CODE | Description | OEM         | Measures            | Ref | ASHIKA CODE | Description      | OEM         | Measures            |
|-----|-------------|-------------|-------------|---------------------|-----|-------------|------------------|-------------|---------------------|
| 1   | 103-02-206  | Axial Joint | 45503-19036 | th: MM14X1.5R L:315 | 4   | 73-02-291   | Tie Rod End      | 45046-29135 | c:12.6 th:FM12X1.25 |
| 2   | 103-02-202  | Axial Joint | 45503-19035 | th: MM14X1.5R L:317 | 5   | 111-02-259  | Tie Rod End      | 45046 19175 | c:12.7 th:FM14X1.5R |
| 3   | 103-02-210  | Axial Joint | 45503-19056 | th: MM14X1.5R L:297 | 6   | 53-02-296   | Ball Joint Lower | 43330-29136 | c:15.9              |