

HILUX (\_N8\_,\_N9\_,\_N11\_) 2X4

08/1988 - 07/1997



**1** 111-02-226



**2** 111-02-227



**2** 111-02-227




**1** 111-02-226

**10** 108-02-203


**10** 108-02-203



**4** 73-02-227




UPPER




**4** 73-02-227



**3** 53-02-235



LOWER



**3** 53-02-235

**5** 27-02-201  
03/1989 ->

**6** 27-02-210

**7** 59-02-215

**8** 59-02-239

**9** 59-02-240

| Ref      | ASHIKA CODE       | Description | OEM         | Measures            | Ref       | ASHIKA CODE       | Description | OEM         | Measures |
|----------|-------------------|-------------|-------------|---------------------|-----------|-------------------|-------------|-------------|----------|
| <b>1</b> | <b>111-02-226</b> | Tie Rod End | 45046-29115 | c.14.8 th:MM17X1.5L | <b>6</b>  | <b>27-02-210</b>  | Tie Rod End | 45450-39165 |          |
| <b>2</b> | <b>111-02-227</b> | Tie Rod End | 45406-29115 | c.14.8 th:MM17X1.5R | <b>7</b>  | <b>59-02-215</b>  | Pitman Arm  | 45490-35140 |          |
| <b>3</b> | <b>53-02-235</b>  | Ball Joint  | 43330-39295 | c:18.2              | <b>8</b>  | <b>59-02-239</b>  | Pitman Arm  | 45490-35130 |          |
| <b>4</b> | <b>73-02-227</b>  | Ball Joint  | 43350-39045 | c:17.1              | <b>9</b>  | <b>59-02-240</b>  | Pitman Arm  | 45490-39315 |          |
| <b>5</b> | <b>27-02-201</b>  | Tie Rod End | 45450-39065 |                     | <b>10</b> | <b>108-02-203</b> | Tie Rod End | 45490-39225 |          |